
Optimal Device Performance Guidance

Cleaning Instructions for Automated Impella Controller (AIC) Purge Disc Retainer

PRODUCT: Automated Impella Controller (0042-0000-US, 0042-0000-EU, 0042-0000-JP, 0042-0000-CA, 0042-0010-US, 0042-0010-EU, 0042-0010-JP, 0042-0010-CA, 0042-0040-US, 0042-0040-EU, 0042-0040-JP, 0042-0040-CA)

DATE: June 2024





REFERENCE DOCUMENTS

- 0042-9025 (AIC User Manual, Europe)
- 0048-9007 (Impella CPSA US IFU)
- 0550-9002 (Impella 5.5 US IFU)
- 10003049 (Impella 5.5 S2 US IFU)
- 0052-9013 (Impella RPSA US IFU)
- 10003286 (Impella RP Flex US IFU)
- 0042-9027 (AIC with SmartAssist User Manual, Europe)
- 0042-9009 (AIC with SmartAssist IFU for Canada)
- 0042-9028 (Impella Ventricular Support Systems, US IFU)
- 0046-9062 (Impella RP US IFU)
- 0042-9021 (AIC Optical, Japan IFU)
- Spec-3766 (Impella 5.5 S2 AU IFU)

REASON FOR NOTIFICATION

To reinforce proper cleaning techniques for the Automated Impella Controller (AIC) housing in accordance with IFU Cleaning Instructions.

RECOMMENDATIONS

It is recommended to clean the Automated Impella Controller housing with mild detergent. Please refer to the “Cleaning” section of your geography’s product specific manual for additional cleaning information.

Johnson&Johnson MedTech

Clinical Support Center
24 hours per day,
7 days a week:
1-800-422-8666 (US)
800 0 22 466 33 (EU)
www.abiomed.com

Abiomed, Inc.
22 Cherry Hill Drive
Danvers, Massachusetts 01923 USA
Voice: 978-646-1400
Facsimile: 978-777-8411
Email: abm_csc_us@its.jnj.com

EC REP **Abiomed Europe GmbH**
Neuenhofer Weg 3
52074 Aachen, Germany
Voice: +49 (0) 241 8860-0
Facsimile: +49 (0) 241 8860-111
Email: csc_emea@its.jnj.com

ABIOMED